# Sony XAV-AX100 USB Cable Replacement

Follow this guide to replace the USB cable on a Sony XAV-AX100 radio.

Written By: Abdulaziz Redha

This document was generated on 2020-11-28 06:35:51 AM (MST).

INTRODUCTION

This repair guide will help you install a new USB cable for your car unit. It will ultimately enhance your experience while connecting the device to your car. This process requires you having a tool kit, specifically, the PH#0 screwdriver and a spudger. With that said, you should be good to go!

🔧 TOOLS:

- Spudger (1)
- Phillips #0 Screwdriver (1)

This document was generated on 2020-11-28 06:35:51 AM (MST).

www.iFixit.com

Step 1 — USB Cable

- Place the device on a flat surface, upside down, so the bottom of the screen would be facing upwards.

- Remove the ten 3.5mm Phillips #0 screws from the back plate.

Step 2

- Use a plastic opening tool to remove the back plate.

- ⓘ Don't remove completely as there will still be cables connected.

This document was generated on 2020-11-28 06:35:51 AM (MST).

Step 3

- Disconnect the USB cable from the display board.

www.iFixit.com

Step 4

- Adjust the rubber holders that are keeping the USB cable still on the motherboard, so you can remove the cable entirely from the inner compartment.

- ⚠ The rubber holders are extremely sensitive to any applied force. Therefore, be careful while turning them around.

Step 5

- Remove the 3.5mm Phillip #0 screw that secures the USB cable to the back panel.

- Pull the USB cable off of the back plate.

To reassemble your device, follow these instructions in reverse order.