![iFixit logo]

HP Pavilion 15-bk020wm Hard Drive Replacement

This guide will assist you in replacing your HP Pavilion 15bk0202wm hard drive.

Written By: Hannah Paine

This document was generated on 2021-05-27 10:29:46 AM (MST).

INTRODUCTION

Your stock hard drive could be too slow for your operating software. Use this guide to replace your current hard drive with one of larger capacity.

TOOLS:

- Phillips #00 Screwdriver (1)
- Spudger (1)
- iFixit Opening Tools (1)

PARTS:

- 1 TB SSD / Upgrade Bundle (1)
- 250 GB SSD / Upgrade Bundle (1)
- 500 GB SSD / Upgrade Bundle (1)
- 2 TB SSD (1)

This document was generated on 2021-05-27 10:29:46 AM (MST).

Step 1 — Keyboard Cover

ⓘ Before you begin, turn the laptop off and unplug it from the power source.

● Remove the 4 computer feet. (Our device didn't have these; they can be taken off with a plastic spudger.)

● Remove the two screw cover strips.

● Remove the two screw cover plugs.

● Unscrew all 12 screws (size: Phillips M2.5×7.0) from the bottom of the computer.

Step 2

- Turn the computer over to the front.

- Open the laptop.

- Use a plastic pry tool to pry up the keyboard cover near the hinge on both the right and left side, and work your way towards the touchpad.

Step 3

- Tilt the keyboard cover up slightly.

- ⚠️ Do not fully remove the keyboard, as it is still attached to the laptop by some cables.

This document was generated on 2021-05-27 10:29:46 AM (MST).

Step 4 — Hard Drive

- Remove the hard drive from the laptop.

- ⓘ Our device did not contain a hard drive.

To reassemble your device, follow these instructions in reverse order.