



URPOWER V2 Ultrasonic Aroma Essential Diffuser Fan Replacement

If your URPOWER V2 Ultrasonic Aroma Essential...

Written By: Lilian Kay



INTRODUCTION

If your URPOWER V2 Ultrasonic Aroma Essential Diffuser is making a buzzing noise, use this guide to replace the Coolcox CC5010M12S fan. The fan can have a faulty blade that creates a buzzing noise when on.

Before beginning make sure there is no water in the device.



TOOLS:

- [Magnetic Project Mat](#) (1)
 - [Phillips #00 Screwdriver](#) (1)
-

Step 1 — fan




- Unplug the Oil Diffuser.

Step 2





- Using a Phillips #00 screwdriver from the iFixit kit, remove all three 10.0 mm screws on the bottom piece.

Step 3




- Remove the bottom piece of the Oil Diffuser.
- ⓘ Be careful not to lose the outside light and air buttons.

Step 4




- Unplug the fan power cord.

Step 5



- Using the Phillips #00, remove two 10.0 mm screws holding the fan onto the base of the diffuser.

Step 6



- Remove and replace the fan.

To reassemble your device, follow these instructions in reverse order.