

How to clean Microtek ScanMaker 5900 surface glass

This guide will show you how to clean the...

Written By: Steven Shaginyan



INTRODUCTION

This guide will show you how to clean the exterior side of the surface glass.



Soft Cloth (1)

Step 1 — Remove serial port connection



- Loosen the screws on the serial port by turning them counter clockwise by hand.
- After loosening the screws, pull the serial port out.

Step 2 — Remove Lid



- Lift lid to its vertical position.
- Pull lid straight up to remove it from the scanner.

Step 3 — How to clean Microtek ScanMaker 5900 surface glass



• Using a soft lint-free cloth clean the surface glass of dust, finger prints, and other debris.

To reassemble your device, follow these instructions in reverse order.