




# Lenovo Edge Thinkpad E431 Screen Replacement

This guide will show you how to replace the...

Written By: Abdullah Muhammad Ashfaq Nadir



# INTRODUCTION

This guide will show you how to replace the screen on a Lenovo ThinkPad Edge E431 laptop.

## TOOLS:

Phillips #00 Screwdriver (1)  
Spudger (1)  
iFixit Opening Tool (1)  
Magnetic Project Mat (1)  
Phillips #0 Screwdriver (1)

## PARTS:


04W3650 - Lenovo Laptop LCD Panel - Genuine (1)

## Step 1 — Battery




- Remove the 2mm Phillips #00 screw from the battery cover.
- Lift the battery cover out of its slot.

## Step 2




- Disconnect the battery cable.

### Step 3 — Screen




- Use the pointed end of a spudger to remove the two screw covers from the bottom corners of the display.

## Step 4



- Remove the two 2mm Phillips #00 screws found at the bottom corners of the display.

## Step 5



- Separate the front bezel from the display using the plastic opening tool.

## Step 6



- Remove the four 2mm Phillips #00 screws from the screen.

## Step 7



- Lay the screen flat on top of the keyboard.

## Step 8



- Peel up the adhesive tape to unlatch the metal retaining bracket on the display cable.

To reassemble your device, follow these instructions in reverse order.