




# 2003-2007 Honda Accord Power Steering Pump Replacement

A video tutorial on how to change an old worn out power steering pump on a 2003-2007 Honda Accord.

Written By: eCuration



This document was generated on 2020-11-24 12:58:51 AM (MST).

## INTRODUCTION

If you are noticing a power steering leak, squealing sound when turning and or difficulty turning then it may be time to replace the power steering pump.

Follow this video tutorial by YouTuber [NutzAboutBolts](#) to complete the repair yourself.



### TOOLS:

- [3/8" Drive Ratchet](#) (1)
- [12mm Deep Socket](#) (1)
- [10mm Deep Socket](#) (1)
- [Hose Clamp](#) (1)
- [Large Needle Nose Pliers](#) (1)
- [Paper Towels](#) (1)
- [Torque Wrench](#) (1)



### PARTS:

- [Power Steering Pump](#) (1)

To reassemble your device, follow these instructions in reverse order.